Work Orde	er ID 97919 50:34 PM		*979	19*						Page 1	_
Revision ID:	D2013-4 Mirror Bracket RH, 212		Accept	*NC	<u> </u>	<b>010</b> (	ገ*	Setup Sta	iV	S1* S2*	_
	2/25/13 Start Qty: 4. 3/15/13 Req'd Qty: 4.	•		Į.	t Item ID: tomer:						
Approvals:	Process Plan: ML5 QC:		•	li li	Date: Date:			Run Sta	I 🗸	R1* R2*	•
Sequence ID/ Work Center ID	Operation Description		Set Up/ Run Hours	То	ol ID Too	l# Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp	»-
Draw Nbr	Revision Nbr										i
D2013	Rev C	- <del></del>					•			S	3 ,
100 *100* Brake NC	NC BRAKE	0	0.00				4			(31°	3-06-18
Brake NC	1-Pur 2-Fla 3-Ber Ident	inch as per template D2013-T3 tten ends of D2013-3 tube as part (1) tube as per Dwg D2013 ify as D2013-3.	per Dwg D2013 using DT854	.5							,
*110 * QC Quality Control	QC5- Inspect part	completeness to step on W/O	0.00 136	<b>?</b> 20			4				
Quality Control											

											DQA:	Date	
NCR:	Yes	/ No				WORK ORDER NON-C	100	VFORM	MANCE / UPD/	ATE			
· · · · · · · · · · · · · · · · · · ·											QA Closed:	Date	•
Work Orde	or.					DISPOSITION				AGAINST DE	PARTMENT	/PROCESS	
· WOIR OIG	-	•				Rework	1		Skid-tube	Crosstube		Water Jet	Engineering
Part No.						Scrap			Machining	Small Fab	Pro	od. Eng. Coor.	Quality
						Use-as-is			noforming	Finishing	Rec/Sto	re/Packaging	Other
NCR I	۷o.					Work Order Update			Large Fab	Composite		Supplier	
		·			,						l c: 0		
Root						ption of work order update	1	Initial	Actio		Sign &		
Cause		Date	Step	Qty		or Non-conformance	Ch	ief Eng	Descrip	tion	Date	Verification	QC Inspector
Doc/Data	Ш							;		•			
Equip/Tooling	Ш												
Operator	Щ	:					İ						
Material	Ш												
Setup	Ш								•			·	
Other	Ш												
Process `	Ш												
Supplier	Ш									•			
Training	Ш												
Unapproved											<u> </u>	<u> </u>	
						F	AUL	T CATE	GORY			· .	
Landi	ng G	iear				General	_	7		F	1		<b>-</b>
	Ш	Bending				Bend	<u></u>	Grain			Ovalized	-	Pressure/Forced
	Ш	Centre No	t Concer	ntric to	o/s	BOM/Route	<u></u>	Hardwa	re		Over/Unde	<b>⊢</b>	Temperature/Cure
		Cracks				Broken/Damaged		Inspect	ion Incomplete		Part Incorre	ect	Weld
		Crushed/0	Crimped.			Burrs		Instruct	ions Incomplete/Un	ıclear	Part Lost/N	lissing	Wrong Stock Pulled
		Cuffs				Contamination		Mainte	enance		Part Moved	l	
		Heat Trea	t			Countersink		Mislabe	eled		Positioned	Wrong	_
	$\Box$	Inspection	Strip in	Tube		Cut Too Short		Misread	t		Power Loss	/Surge	Other

Offset

Out of Calibration

Out of Sequence

Outside Dimensions

Turning Sequence

Wave/Twist in Tube

Ripples in Bend

Torque Waves in Extrusion

Drill Holes

Drawing

Finish

Folio

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G

Work Orde		)19		*970								Pag	e 2	
Item ID: Revision ID: Item Name:	D2013-4 Mirror Bracket		<b>+</b> 4 <b>+</b>	Accept			<b>040</b>	100	)*	Setup	Start Stop	IV	S1* S2*	
Start Date: Required Date: Reference:	2/25/13	Start Qty: 4.00 Req'd Qty: 4.00	*4* *4*			t Item II stomer:	D:	_		D.	<b>54</b> 0 m4			
Approvals:		n:					Date:			Run	Start Stop	171	R1 <sup>*</sup> R2 <sup>*</sup>	,
Sequence ID/ Work Center I 120 *120* Packaging Packaging	<b>D</b>	Operation Description Identify as per dwg & St	ock Location:_W/	Set Up/ Run Hours 0.00	T	ool ID	Tool#	Plan Code	Accep Qty	Qt	<b>y</b>	Reject Number	·	
*130 *130* QC Quality Control		QC21- Final Inspection  Memo	- Work Order Release	0.00							13,	/6/c	97(	

Mrons

NCR:	Yes	/ No				WORK ORDER NON-C	O	NFORM	MANCE / UPDATE		QA Closed:	Date			
						ı	1				JA Closea:	Date	:		
Nork Orde	er: .					DISPOSITION .									
Part N	Part No Rework							ı	Skid-tube Crosstube  Machining Small Fab	_		Water Jet d. Eng. Coor.	Engineering Quality Quality		
NCR I	NCR No.				Use-as-is Work Order Update		Thermoforming Finishing Large Fab Composite			Rec/Store/Packaging Other Supplier					
Root		Description of work order up				ption of work order update		nitial	Action		Sign &	· <del></del> · · ·			
Cause		Date	Step	Qty		or Non-conformance	Ch	ief Eng	Description		Date	Verification	QC Inspector		
oc/Data												1			
	H						ł					Í	` [• ´		
perator Naterial							ļ.					<i>f</i>			
etup										ļ		* <i> </i>			
ther						•						1			
rocess	Н											'	·		
upplier										$\cdot$		1	·		
raining		,					١								
napproved															
						F	AUL	T CATE	GORY						
Landi	ng G	Gear				General				<del>, _ ,</del>		_	$\neg$		
		Bending				Bend		Grain		Ш	Ovalized		Pressure/Forced		
		Centre No	ot Concer	ntric to	o/s	BOM/Route		Hardwa	ire ·		Over/Under	tolerance	Temperature/Cure		
		Cracks				Broken/Damaged		Inspecti	ion Incomplete	Ш	Part Incorre	ct [	Weld		
		Crushed/0	Crimped.			Burrs	L	Instruct	ions Incomplete/Unclear	Ш	Part Lost/M	ssing	Wrong Stock Pulled		
		Cuffs			·	Contamination		Mainte	enance		Part Moved				
		Heat Trea	it			Countersink		Mislabe	eled		Positioned V	Vrong			
		Inspection	n Strip in	Tube	·	Cut Too Short		Misread	t l		Power Loss/	Surge	Other		
	П	Ripples in	Bend			Drill Holes		Offset							
		Torque W	aves in E	xtrusio	n	Drawing		Out of (	Calibration						
		Turning S				Finish		Out of S	Sequence						
	Wave/Twist in Tube					Folio		Outside	e Dimensions						

DQA:

Date:

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G

## **Picklist Print**

March-01-13 1:50:33 PM

Work Order ID:

97919

Parent Îtem:

D2013-4

Parent Item Name:

Mirror Bracket RH, 212

**Comments:** 

IPP Rev:A

New Issue 05-11-01 JLM

**Start Date: 2/25/13** 

Required Date: 3/15/13

Start Qty: 4.00

Required Qty: 4.00


Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty		Date Issued	Status
M304TR0.750W.049		Purchased	No			100	f	495.6911	1.9473	8.199158	<	'n	11/2/21
304 RD Tube .750 x .049V	<i>l</i>					ą.	-	٠. خ			့လု		12107 106

Location Loc Qty MAT017 495.6911325 122312 26.37 0.0000325 122468 124768 469.3211

		DQA:	Date:	
NCR: Yes / No	WORK ORDER NON-CONFORMANCE / UPDATE			

									QA Closed:	Date	<u> </u>				
Work Orde	er:	<del></del>			DISPOSITION		AGAINST DEPARTMENT/PROCESS								
Part N			•		Rework Scrap		Skid-tube Machining	Crosstube Small Fab	4	Water Jet d. Eng. Coor.	Engineering Quality				
NCR No.					Use-as-is Work Order Update	Ther	moforming Large Fab	Finishing Composite	Rec/Sto	re/Packaging Supplier	Other				
Root				Descript	ion of work order update	Initial	A	ction	Sign &						
Cause	Date	Step	Qty	or	Non-conformance	Chief En	g Des	cription	Date	Verification	QC Inspector				
Doc/Data															
Equip/Tooling										`					
Operator						1	ļ								
Material						ļ									
Setup			_												
Other			Ā												
Process															
Supplier															
Training															
Unapproved						<u> </u>	<u> </u>		<u> </u>						
						AULT CAT	EGORY	· · · · · · · · · · · · · · · · · · ·							
Landi	ng Gear				General				7	г	<del></del>				
	Bending			<b>+</b>	Bend	Grain		-	Ovalized		Pressure/Forced				
	Centre N	ot Conce	ntric to (		SOM/Route	Hardv		<u> </u>	Over/Under	<u> </u>	Temperature/Cure				
	Cracks			<b>—</b>	Broken/Damaged	<b></b>	tion Incomplete	_	Part Incorre	F	Weld				
	<b>⊢</b> ⊣	/Crimped		-	burrs	$\vdash$	ctions Incomplete	/Unclear	Part Lost/M		Wrong Stock Pulled				
	Cuffs			<b>├</b>	Contamination	<b></b> -	tenance		Part Moved		•				
	Heat Tre	at			Countersink	Mislal			Positioned \	· · ·	<b>—</b> .				
	<b>⊢</b> ⊸	on Strip in	Tube		cut Too Short	Misre			Power Loss,	/Surge	Other				
	Ripples i				Orill Holes	Offset									
	Torque	Waves in I	Extrusio	ր ∐ն	Drawing	$\vdash$	f Calibration								
•	Turning	Sequence	!	<b>—</b>	Finish Out of Sequence										
	Wave/T	wist in Tu	be	F	olio	Outside Dimensions									

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G



Copyright 1990 by DART AEROSPACE LTD